LINEAR ACTUATOR


LA50



Main Spec:

Туре	LA50				
Input option	12/24/36/48VDC				
Load	1000~15000N 100~1500KG 220~3300LBS				
Speed option	2.5~160mm/s 0.1~6.4inch/s				
Limited switch	with				
Duty cycle	25%				
House material	Aluminum				
Inner tube material	Stainless steel				
Stroke length option	0~1500mm 0~600inch				
Color	Black				
Operation temperature	-26℃ ~+65℃				
Signal feedback	Potentiometer/Hall sensor				
IP	IP65				
Certificate	CE				

Customized order example:



Input Load Unload speed Stroke Retracted length Cable length

G: Customer's special requirement

Spec:

Туре	Load: N	Unload speed: MM/S	Load speed: MM/S	12V	Max cur 24V	rent A 36V	48V
LA50-1	1000	160	80	20	13	6	3
LA50-2	1500	100	65	20	12	5	2.6
LA50-A	2000	65	30	17	8.5	6.5	4
LA50-B	2000	50	30	17	8.5	6.5	4
LA50-C	2000	40	25	16	7.5	5.5	3.5
LA50-D	3000	20	14	17	8.5	6	3.6
LA50-E	4000	15	12	16	7.5	5.5	3.5
LA50-F	7000	12	9	11	5.5	4	2.5
LA50-G	9000	8.5	5	10	5.5	4	2.6
LA50-H	10000	5	3	11	6	4	2.6

Normal drawing cable:

For ACME lead screw Lmin = Mini retracted length= 250mm + Stroke


For Ball Screw lead screw Lmin = Mini retracted length= 260mm + Stroke

Lmin means the length when linear actuator 100% fully retracts, meanwhile, it will touch the tail limited switch, stop automatically, very safe.

Lmax = Max extended length= Lmin + Stroke = 250mm + 2*Stroke

Lmax means the length when linear actuator 100% fully extends, meanwhile, it will touch the head limited switch, stop automatically, very safe.


Brown and black cable is for motor power + and -




Force , Speed & Current:

Linear Actuator Designer

Help@OkeyGoGo.com



The customers have many different applications for linear actuator. We can supply varies of front and rear connector to meet your requirements. Here is the drawing.




Cable

With potentiometer

Brown and black cable is for motor power + and -

Red, yellow and blue cable is for Potentiomter



With Hall Effect Sensor

Brown and black cable is for motor power + and -Red,black,yellow and blue cable is for hall sensor

